

Oil Field Environmental Incident Summary

Incident: 20160208104543 **Date/Time of Notice:** 02/08/2016 10:45

Responsible Party: ONEOK Rockies Midstream

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 2/8/2016 **Time Incident:** 07:15

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 98

Sec: 35

Qtr: SE

Location Description: ONEOK Garden Creek Plant,
3007 121st Ave NW
Watford City, ND 58854

Submitted By: Byron Skaley

Received By:

Contact Person: Byron Skaley
2700 Lincoln Ave SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1200 Feet

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Gallons	5	Gallons		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk.

Areal Extent:

Potential Environmental Impacts:

No Potential environmental impacts

Action Taken or Planned:

The unit was shut down from the control room and Operations were able to access the pump to block it in. Product and impacted soil will be cleaned up

Wastes Disposal Location:**Agencies Involved:****Updates**

Date: 2/8/2016 **Status:** Reviewed - Follow-up Required**Author:** O'Gorman, Brian**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Release, due to equipment failure, affected topsoil on the facility according to the report. Further followup needed.

Date: 3/15/2016 **Status:** Inspection**Author:** Washek, Sandi**Updated Oil Volume:** 5.00 gallons**Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Arrived on site at 9:15 a.m. and met with company rep. Inspected area of impact. The soil and gravel had been cleaned up, and new gravel had been spread on the site. Waste was sent to Nuverra Waste facility. No additional follow-up needed.